


## Figure B Bookcase




### We ordered the following supplies from rockler.com:

- Deluxe Murphy Bed Hardware Kit, Item No. 46025
- Murphy Bed Box Light Kit, Item No. 31965
- Single Bookcase Light Kit, Item No. 31953
- 96mm Arts & Crafts Pulls (2), Item No. 10988
- 96mm Arts & Crafts Backplates (2), Item No. 11014
- 3" Arts & Crafts Pulls (2), Item No. 10962
- 3" Arts & Crafts Backplates (2), Item No. 11001
- 1-1/4" Square Arts & Crafts Knobs (5), Item No. 10910
- 10" Series 757 100-lb. Slides (two pairs), Item No. 48386
- 95° Thick Door Frameless Inset Hinges (two pairs), Item No. 55879


Continued on p. 86

Mackintosh Table, continued from p. 33

# **Figure E**Top detail



### **Figure F** Apron detail



## Statement of ownership, management, and circulation

Statement required by the Act of August 12, 1970, Section 3685, Title 39, United States Code, showing the ownership, management and circulation of THE FAMILY HANDYMAN (USPS 515-930) published monthly (except bimonthly in December/January and July/August) 10 times a year, at 1610 N. 2nd St., Suite 102, Milwaukee, WI 53212-3906, as filed on Sept. 30, 2014. Annual subscription price: \$24.

The names and addresses of the publisher, editor and managing editor are: Publisher, Russell S. Ellis, 750 Third Ave., New York, New York County, NY 10017; Editor, Ken Collier, 2915 Commers Drive, Suite 700, Eagan, Dakota County, MN 55121; Managing Editor, Travis Larson, 2915 Commers Drive, Suite 700, Eagan, Dakota County, MN 55121.

The owner is Home Service Publications, Inc., 750 Third Ave., New York, NY 10017.

Known bond holder: WRC Media, 750 Third Ave., New York, NY 10017.

The Family Handyman

Issue date for circulation data: October 2014

Average number of copies of each issue during preceding 12 months, and of the single issue published nearest to filing date, respectively, is as follows:

	Average	Single Issue
Total number of copies printed		
(net press run)	1,183,113	1,185,178
Mail subscriptions	1,004,596	998,219
Paid distribution—sales through		
dealers and carriers, street vendors		
and counter sales	58,522	63,737
Total paid distribution		
	1,063,118	1,061,956
Free or nominal-rate distribution		
	24,068	24,136
Total distribution		
	1,087,186	1,086,092
Copies not distributed		
	95,927	99,086
Total		
	1,183,113	1,185,178
Percent paid and/or requested		
circulation	98%	98%
I certify that the statements made by	me above are	correct and
complete.		

Jim Woods, Vice President, Planning, Consumer Marketing

Murphy Bed Bookcase, continued from p. 25

## **Cutting List**

KEY	QTY.	DIMENSIONS	NAME
3/4"	OAK	PLYWOOD	

3/-	UAK	PET WOOD	
Α	2	28-3/4" x 76-1/2"	Bed face panels
В	2	15-1/2" x 82-1/8"	Bed cabinet verticals
С	1	15-3/8" x 58-3/8"	Bed headboard
D	1	15-9/16" x 58-1/2"	Bed cabinet top
E	1	14-3/4" x 58-3/8"	Bed header panel
F	4	11-1/2" x 72-3/8"	Bookcase verticals
G	1	7-5/8" x 56"	Head rail
Н	1	2-3/4" x 56"	Foot rail
J	2	5-1/8" x 75-1/4"	Side rails
K	2	5-3/4" x 59-3/8"	Bed fascia box front/back
L	2	5-3/4" x 14-1/2"	Bed fascia box sides
M	2	11-9/16" x 19-5/16"	Bookcase top
N	4	11-1/2" x 18-1/2"	Bookcase top/bottom shelves
Р	2	11-1/4" x 18-1/2"	Bookcase middle shelves
Q	2	11-1/4" x 13-1/2"	Pullouts
R	4	10-1/2" x 18-1/4"	Adjustable shelves
S	4	4-3/4" x 19-3/4"	Bookcase fascia box front/back
Т	4	4-3/4" x 10-1/2"	Bookcase fascia box sides
U	2	15-3/8" x 16-1/4"	Doors

### 1/2" BIRCH PLYWOOD OR MDF

V	1	16" x 59-3/8"	Bed fascia trim boards
W	2	12" x 19-3/4"	Bookcase fascia trim boards

### 1/4" OAK PLYWOOD

Χ	2	28" x 75"	Mattress supports
Υ	2	19-1/4" x 19-3/8"	Bookcase back

3/4"	OAK		
Z	1	5-3/4" x 60"	Bookcase base
AA	1	2-3/8" x 80"	Bed base
BB	2	2-3/4" x 58-3/8"	Bed header front/back
CC	1	2-3/4" x 182"	Top trim
DD	4	2" x 72-3/8"	Face frame stiles
EE	4	2" x 16"	Face frame rails
FF	2	3/4" x 16"	Middle shelf edges
GG	2	1-3/4" x 15-7/8"	Pullout fronts
HH	4	1-1/2" x 11"	Pullout sides
JJ	4	1-1/4" x 18-3/8"	Adjustable shelf trim
KK	2	1-1/2" x 5-1/8"	Side rail end trim
LL	2	3/4" x 76-1/2"	Side rail edges
MM	2	3/4" x 82-1/8"	Bed cabinet edges
NN	1	3/4" x 54-1/4"	Leg support rail

1/2" x 168"

E 0/4" v E0 7/0"

1/	4"	OAK

PP

لاالا	1	5-3/4" x 59-//8"	Bed fascia front
RR	2	5-3/4" x 16-1/4"	Bed fascia sides
SS	2	4-3/4" x 20"	Bookcase fascia fronts
TT	2	4-3/4" x 12-1/4"	Bookcase fascia sides
UU	3	4-3/4" x 19-1/4"	Bed panel drawer fronts
VV	4	4" x 22-15/16"	Bed panel bottom rails
WW	4	3" x 40"	Bed panel upper stiles
XX	4	3" x 30"	Bed panel lower stiles
YY	4	2-1/2" x 22-15/16"	Bed panel upper rails
ZZ	2	2" x 33-1/4"	Bed panel upper mullions
AAA	2	2" x 23-1/2"	Bed panel lower mullions
BBB	2	3/4" x 58"	Bed panel horizontal dividers
CCC	4	2" x 16-1/2"	Door panel stiles
DDD	2	2-1/2" x 12"	Door panel bottom rails
EEE	2	2" x 12"	Door panel top rails
FFF	1	3/4" x 600"	Edging

Fascia trim


Dad foosis front

#### 3/4" POPLAR

GGG	10	1-1/2" x 54-1/2"	Bed frame struts
HHH	2	1-1/2" x 75"	Bed frame sides
JJJ	2	1-1/2" x 14-3/4"	Bed header mounting cleats
KKK	4	1-1/2" x 11-1/2"	Bottom shelf cleats
LLL	4	1-1/4" x 11-1/4"	Middle shelf cleats
MMM	2	1" x 17"	Top shelf front cleats
NNN	4	1" x 11-1/2"	Ton shelf side cleats



**Figure C**Bookcase vertical



**Figure D** Plywood cutting diagrams

